


1. FT7011 / FTD7011 平形下擺盲縫用零件列表
 Parts List For FT7011 / FTD7011 Bottom Hemming



序號 Ref.No.	名稱 Description	針距 Distance Of Needles			
		4.0	4.8	5.6	6.4
1	壓腳 Presser Foot	5222PF11400	5222PF11480	5222PF11560	5222PF11640

1. FT7011 / FTD7011 平形下擺盲縫用零件列表 Parts List For FT7011 / FTD7011 Bottom Hemming

序號 Ref. No.	物料編號 Parts No.	名稱 Description	單位用量 Amt. Req.
1	-----	壓腳 Presser Foot (see Left Page) -----	1
2	2280110102	左導模 Fabric Guide (L) -----	1
3	2210110103	右導模 Fabric Guide (R) -----	1